

Gravity Plus®

Anti-Sticking Agent



Keeps Coal and Ash from Sticking to Surfaces

Gravity Plus is a ready-to-use, special formulation which forms a super-slippery, flexible coating that eliminates sticking.

Gravity Plus is highly resistant to severe abrasion and impact typical in coal mining and processing, has self-healing action that prolongs coating life and does not chip or flake.

Gravity Plus is applied using a chemical spray applicator (Switch Treator®). The treated surface is ready for use immediately. Gravity Plus must be applied for several applications so that the surface becomes properly "conditioned" or coated.


The Gravity Plus formula is environmentally friendly and considered non-hazardous to your health.

Ideal for:

- Bins
- Silos
- Chutes
- Hoppers
- Rail Cars
- Truck Beds
- Bucket Elevators

Surface preparation

Normally it is sufficient to brush off fines and grit from the surface. The particles of the formulation must come in contact with the metal surface for proper adhesion and abrasion resistance. If this is not feasible, several liberal applications are recommended during the initial application period.



Gravity Plus is highly resistant to severe abrasion and impact, has self-heating action that prolongs coating life and does not chip or flake.