



EnviroKleen Application

Visual Summary

Squaw Creek National Wildlife Refuge, Missouri

July 23-24, 2014





Road conditions prior to treatment were dusty, even at low speeds



**Pre-wetting with
water truck**



Road preparation and compaction



EnviroKleen application



**Close-up of
application edge**



**View of freshly treated
northern section**



Visual inspection by refuge staff



**View from back of truck
while driving north on
untreated section**



**Transition onto
EnviroKleen-treated
section**